

From: [Owens, Rock \(CAO\)](#)
To: [Miller, Garyg](#)
Cc: [Jacquelyn Young](#); [Utley, Sarah \(CAO\)](#); [Allen, Bob \(PCS\)](#)
Subject: Re: SJRWP Safety Req
Date: Thursday, March 31, 2016 9:47:40 AM

Gary,

I'm assuming the temporary buoys recently placed at the site are depicted by small bright orange globes shown in the photo recently sent to you by Jackie Young. If I'm correct, one of the buoys appears to have become untethered and is resting on the western bank. I suppose the explanation that these buoys are "temporary" helps explain this malfunction

While it's comforting to know better replacements are on their way, it seems important that this current situation be corrected as soon as possible.

Thanks
Rock

Sent from my Verizon Wireless 4G LTE DROID

Jacquelyn Young <jeyoung@texanstogether.org> wrote:

I received messages this evening from a Channelview resident complaining that several of the new buoys are floating away. One was mentioned to be near the center of the Pits. I just so happen to be out in the community this afternoon and snapped photos as we crossed over the River. I did not notice the buoy captured in my photos at the time, but I now see that I captured the buoy along the central berm. See attached.

Viewing the Site this afternoon I was happy to see the new safety equipment on Site. However, I am now disappointed to learn that the safety measures have not even been in place but a couple of weeks (at most) and are proving problematic. I'm not sure what went wrong or why buoys are floating away but this once again reinstates the lack of confidence we have in the PRPs conducting any work on Site.

I've reported this to Gary Miller.

Sincerely,
Jackie Young



9768806